



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Nov 18, 2019 4:34:46 PM MST
Server Receive Date:	Nov 18, 2019 4:36:52 PM MST
Reference Number:	20191118-18123320379
Location:	557 Airpark Dr, Durango, CO 81303, USA Nov 18, 2019 4:36:04 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Nov 18, 2019
Well Name	MCCAW, LEROY GAS UNIT B 2
API Number	50670891000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up weed debris on location.

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up weed debris on location.

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed

Sprayed musk thistle populations.




Completed work description
Completed work description of corrective action 4
Additional photos

Sprayed musk thistle populations.
Sprayed musk thistle populations.



Additional photos



Completed work description

Summary of all work completed

Cleaned up weed debris and sprayed musk thistle populations.

Cleaned up weed debris and sprayed musk thistle populations.