



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Dec 9, 2019 9:14:20 AM MST
Server Receive Date: Dec 9, 2019 9:16:36 AM MST
Reference Number: 20191209-18125639445
Location: 557 Airpark Dr, Durango, CO 81303, USA
Dec 9, 2019 9:13:54 AM MST [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Dec 6, 2019
Location Name (Other) Margaret Montgomery A1
API Number 50670752100
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

mowing weed debris

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

mowing weed debris



Completed work description
 Completed work description of corrective action 4
 Summary of all work completed

mowing weed debris
 mowed weed debris around equipment and in the
 reclamation area
 mowed weed debris around equipment and in the
 reclamation area