

Inspection Photos
Location Name: Jack Mleynek #1
Location ID: 318147



Photo 1 Operator and emergency information not legible



Photo 2 WH sign

Inspection Photos
Location Name: Jack Mleynek #1
Location ID: 318147



Photo 3 Dead weeds around WH and PU



Photo 4 Dead weeds / PU fence in disrepair



Inspection Photos
Location Name: Jack Mleynek #1
Location ID: 318147



Photo 5 PU fence in disrepair