

Inspection Photos  
Location Name: Mleynek 28-15 JI  
Location ID: 331054



Photo 1 WH sign

Photo 2 Unused WH equipment

Inspection Photos  
Location Name: Mleynek 28-15 JI  
Location ID: 331054



Photo 3 Unused ancillary equipment

Photo 4 Horiz. Heated separator

Inspection Photos  
Location Name: Mleynek 28-15 JI  
Location ID: 331054



Photo 5 Gas Meter Run

Photo 6 TB signs

**Inspection Photos**  
**Location Name: Mleynek 28-15 J1**  
**Location ID: 331054**



**Photo 7 TB**