

Inspection Photos
Location Name: Josephine B Miles #3
Location ID: 318612



Photo 1 WH sign

Photo 2 WH/PU

Inspection Photos
Location Name: Josephine B Miles #3
Location ID: 318612



Photo 3 dead weeds around PU base

Photo 4 Dead weeds around PU base

Inspection Photos
Location Name: Josephine B Miles #3
Location ID: 318612



Photo 5 dead weeds around ancillary equipment.