

Inspection Photos

Location Name: VAN WYKE-65N63W /32SENW

Location #: 332268



Colorado Oil & Gas Conservation Commission
40.35786, -104.46244, 1380.0m, 349°
10/21/2019 02:49:08 PM

Photo #1

Van Wyke 22-32 (05-123-22064) Wellsite

Temporarily Abandoned | TA

**Invalid Operator name posted at wellsite
prior insp.**



Colorado Oil & Gas Conservation Commission
40.35787, -104.4624, 1377.0m, 354°
12/10/2019 02:11:24 PM

Photo #2

Van Wyke 22-32 Wellsite

Temporarily Abandoned | TA

Valid Operator name NOW posted at wellsite

Inspection Photos

Location Name: VAN WYKE-65N63W /32SENW

Location #: 332268



Photo #3

Van Wyke 21-32, 22-32, 4-2-32 Battery

Shut-down | Inactive

prior insp.