

Nate Springs 3
API: 05-103-09822
Inspection: 679706513



Photo 1. Location.

Nate Springs 3
API: 05-103-09822
Inspection: 679706513



Photo 2. Pump jack.

Nate Springs 3
API: 05-103-09822
Inspection: 679706513



Photo 3. Tank battery.



Nate Springs 3
API: 05-103-09822
Inspection: 679706513



Photo 4. Tank label.