

Inspection Photos

API: 05-071-08836

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/10/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-08336 | Date: 12/10/2019

Inspection Photos



Photo 1. Facing toward the location. Sign is posted. Vegetation is well established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08336 | Date: 12/10/2019

Inspection Photos



Photo 2. Facing northwest at the location. There is a well marker for the PA well on location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08336 | Date: 12/10/2019