

Inspection Photos

API: 05-071-08840

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/10/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08840 | Date: 12/10/2019

Inspection Photos



Photo 1. There is signs of erosion occurring along the road at Lat/Long:37.209713, - 104.935704.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08840 | Date: 12/10/2019

Inspection Photos



Photo 2. Facing toward the location. Sign is posted. Vegetation is well established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08840 | Date: 12/10/2019

Inspection Photos



Photo 3. Facing toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08840 | Date: 12/10/2019

Inspection Photos



Photo 4. Facing north at the location. There is a well marker for the PA well on location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08840 | Date: 12/10/2019