

Inspection Photos

API: 05-071-08977

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/10/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08977 | Date: 12/10/2019

Inspection Photos



Photo 1. Well sign is installed at location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08977 | Date: 12/10/2019

Inspection Photos



Photo 2. Facing southwest toward the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08977 | Date: 12/10/2019

Inspection Photos



Photo 3. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08977 | Date: 12/10/2019