

Construction and Stormwater Inspection

December 9, 2019

Operator: VERDAD RESOURCES LLC- #10651

Location ID: 469568

Inspection Document #: 697500894

Weld County, CO

NWSE Section 12 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Safi /1224
Location ID: 469568



Photo 1. Photo taken from the entrance of location, facing North. Photo illustrates Operator has mobilized equipment to the location but has not yet started construction activities.

Inspection Photos
Location Name: Safi /1224
Location ID: 469568



Photo 2. Photo taken from the entrance of location. Photo illustrates survey stake as the ROW for the access entrance.