

# Inspection Photos Location #412676



LOCATION



DEBRIS



# Inspection Photos Location #412676



DEBRIS



DEBRIS

# Inspection Photos Location #412676



DEBRIS



DEBRIS

## Inspection Photos Location #412676



**DEBRIS**



**UNUSED EQUIPMENT**

# Inspection Photos Location #412676



COGCC  
89.5419, -107.57323, 1979.0m, 350°  
12/11/2019 12:22:48 PM

**UNUSED EQUIPMENT**



COGCC  
89.54192, -107.57343, 1977.0m, 41°  
12/11/2019 12:28:10 PM

**UNUSED EQUIPMENT**

# Inspection Photos Location #412676



**LEAKING FITTINGS PUMPER FIXED WHILE ONSITE**



**LEAKING FITTINGS PUMPER FIXED WHILE ONSITE**

# Inspection Photos Location #412676



**LEAKING FITTINGS**



**LEAKING FITTINGS**

# Inspection Photos Location #412676



**LEAKING FITTINGS**



**UNUSED EQUIPMENT**

## Inspection Photos Location #412676



**UNUSED EQUIPMENT**



**STARTER FLUID ON TOP OF BURNER TUBE**



# Inspection Photos Location #412676



**STARTER FLUID ON TOP OF BURNER TUBE**