

# Final Reclamation Inspection

December 9, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 305428

Inspection Document #: 697500898

Weld County, CO

SWSE Section 13 T1N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BRANDT #34-13  
Location ID: 305428



**Photo 1.** Photo taken from the tank battery location, facing West. Photo illustrates the Operator has performed additional reclamation activities in response to the previous corrective action inspection with the evidence of drill rows, straw crimped mulch and some germination.

Inspection Photos  
Location Name: BRANDT #34-13  
Location ID: 305428



**Photo 2.** Photo taken from the tank battery location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: BRANDT #34-13  
Location ID: 305428



**Photo 3.** Photo taken from the tank battery location, facing North. Photo illustrates the well location is currently fallow. COGCC staff will conduct a follow up inspection at a future date to ensure compliance with vegetative standards.