

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2019

Submitted Date:

12/11/2019

Document Number:

693501947**FIELD INSPECTION FORM**

Loc ID 455317 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455304	WELL	DG	06/07/2019		014-20746	Livingston S19-25-9N	DG

General Comment:

Inspected Facilities

Facility ID: 455304 Type: WELL API Number: 014-20746 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 12-4-2019
 Complaint Contacted:
 Date: 12-5-2019 Time: 8:24AM via phone
 Location ID #455317
 Location name: Livingston
 Inspection Document # 693501869
 Complaint Document #200448385
 Nature of Complaint: Noise
 Field Inspector Actions:
 On 12-04-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Kim Livingston 4793 Raven Run Broomfield CO stated the issues were occurring outside of complainants home.
 On 12-5-19-2019, I attempted to make contact with the complainant who indicated that on 12-04-19 she experienced a Humming (like a running car outside their home). Noise started after 9 PM and continued throughout the night. I explained the fracing process to the complainant.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual noise in or around location. After reviewing third party sound study data, location is with in compliance. Sound study data will be attached to compliant inspection form.

 Weather conditions: Raining
 See inspection document #693501869 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See inspection doc#693501869 for full inspection. Third party sound study is attached to complaint inspection.	silverr	12/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501948	Sound data	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011260