

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17NENW

Location ID: 334068



Photo #0228 photo from NW corner of location.



Photo #0229 Diesel tank capacity not labeled.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17NENW

Location ID: 334068



Photo #0230 Unmarked drum inside tank containment.



Photo #0231 trash inside containment.