

Inspection Photos

Location Name: ROTHE-65N63W /31NWSW

Location #: 305177



Photo #1

Rothe 13-31 (05-123-22601) Wellsite

Shut-In | SI

Weeds
prior insp.



Photo #2

Rothe 13-31 Wellsite

Shut-In | SI

Weeds: Removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: ROTHE-65N63W /31NWSW

Location #: 305177



Photo #3

Rothe #1, 13-31, CSW-31 Battery

Shut-down | Inactive

prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources