

Inspection Photos
Location Name: ROTHE-65N63W /31SWSW
Location #: 306070



Photo #1
Rothe CSW-31 (05-123-23945) Wellsite
Temporarily Abandoned | TA
Weeds
prior insp.



Photo #2
Rothe CSW-31 Wellsite
Temporarily Abandoned | TA
Weeds: Removed

Inspection Photos

Location Name: ROTHE-65N63W /31SWSW

Location #: 306070



Photo #3

Rothe #1, 13-31, CSW-31 Battery

Shut-down | Inactive

prior insp.

