

Inspection Photos

API: 05-071-07199

Operator: TIMBER CREEK OPERATING

Inspection Date: 12/12/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07199 | Date: 12/12/2019

Inspection Photos



Photo 1. There is a constant flow of water coming from the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07199 | Date: 12/12/2019

Inspection Photos



Photo 2. Water from well leakage is shown along the surface to this point.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07199 | Date: 12/12/2019

Inspection Photos



Photo 3. Well sign is posted at location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07199 | Date: 12/12/2019