

Inspection Photos  
Location Name: Shaw tank battery  
Location ID: 446599



Photo 1 TB sign

Photo 2 TB

Inspection Photos  
Location Name: Shaw tank battery  
Location ID: 446599



Photo 3 Gas meter run, dead weeds around skid

Photo 4 Horiz. Heated Sep. dead weeds inside fencing


Inspection Photos  
Location Name: Shaw tank battery  
Location ID: 446599



Photo 5 ECD

Photo 6 Dead weeds inside berm of TB

**Inspection Photos**  
**Location Name: Shaw tank battery**  
**Location ID: 446599**



**Photo 7 Stained soil at base of crude oil tank**

**Photo 8 Stained soil under possibly leaking valve TB load line**