

Inspection Photos
Operator: BP America
Location/API #: 067-07727
Date: 12-10-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is in a dormant vegetative condition, and appears to be progressing with grasses such as sand drop seed and western wheatgrass.



Photo 3. View of reference area, comprised of irrigated crop field.