

Crumley* Jack, Tuttle-Walker 1
121-09349
Inspection #688306542
12/13/2019
Final Reclamation Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Colorado Oil and Gas Conservation Commission

40.10069, -103.44721, 4540.7ft, 182

12/13/2019 02:48:07 PM



Colorado Oil and Gas Conservation Commission

40.10078, -103.44726, 4537.4ft, 192°

12/13/2019 02:41:20 PM




Colorado Oil and Gas Conservation Commission
40.10074, -103.44735, 4534.1ft, 173°
12/13/2019 02:41:37 PM



Colorado Oil and Gas Conservation Commission

40-10068, -103.44737, 4534.1ft, 16.7

12/13/2019 02:41:46 PM



Colorado Oil and Gas Conservation Commission

40.10067, -103.44733, 4534.1ft, 150°

12/13/2019 02:41:51 PM