

Impetro Resources LLC, Walker\*Ruth 1  
121-06866

Inspection #688306555

12/13/2019

Routine Inspection



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission

40 0978 -103 44606, 4521.0ft, 254'

12/13/2019 02:45:20 PM



Colorado Oil and Gas Conservation Commission  
40.09777, -103.44604, 4527.6ft, 320°  
12/13/2019 02:45:28 PM





Colorado Oil and Gas Conservation Commission  
40.09785, -103.44606, 4530.8ft, 317°  
12/13/2019 02:45:41 PM



Colorado Oil and Gas Conservation Commission

40-09789, -103-44609, 4530.8ft, 51°

12/13/2019 02:45:50 PM






Colorado Oil and Gas Conservation Commission

40.09777, -103.44604, 4527.6ft, 248°

12/13/2019 02:45:31 PM



IMPETRO RESOURCES LLC  
Tuttle Walker Lease  
SE-NW-NW Sec 32 T2N  
R54 W 6M





Colorado Oil and Gas Conservation Commission  
40.10317, -103.44706, 4540.7ft, 59°  
12/13/2019 02:50:33 PM





Colorado Oil and Gas Conservation Commission  
40.10316, -103.44696, 4537.4ft, 129°  
12/13/2019 02:50:53 PM




Colorado Oil and Gas Conservation Commission  
40.10316, -103.44695, 4537.4ft, 118°  
12/13/2019 02:50:55 PM





Colorado Oil and Gas Conservation Commission  
40.10349, -103.44738, 4550.5ft, 178°  
12/13/2019 02:52:13 PM



Colorado Oil and Gas Conservation Commission  
40.10318, -103.44743, 4550.5ft, 228°  
12/13/2019 02:49:36 PM





Colorado Oil and Gas Conservation Commission

40.10316, -103.44746, 4540.7ft, 287°

12/13/2019 02:49:42 PM



Colorado Oil and Gas Conservation Commission  
40.10318, -103.44735, 4544.0ft, 254°  
12/13/2019 02:49:27 PM





Colorado Oil and Gas Conservation Commission  
40.10315, -103.44748, 4540.7ft, 241°  
12/13/2019 02:49:46 PM



Colorado Oil and Gas Conservation Commission  
40.10317, -103.44733, 4544.0ft, 287°  
12/13/2019 02:49:22 PM