

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2019

Submitted Date:

12/16/2019

Document Number:

697600675

FIELD INSPECTION FORM

Loc ID 327647 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , Anadarko | | COGCCinspections@Anadarko.com | |
| | | Gregory_Hamilton@oxy.com | |

General Comment:

inspection of well and shared battery nearby
battery signs indicate production facilities are used by
123-14655 (not on location and recently P&A),
123-14654 (not on location and recently P&A)
and
123-14654

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------|
| Emergency Contact Number: | | | |
| Comment: | emergency contact information on wellhead sign and on battery sign | | Date: |
| Corrective Action: | | | |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment: no spills observed at surace around wellhead and battery

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|-------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-------------------------------|-----|-------|-----------------|
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |

| | | | |
|-----------------------------------|-----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLs | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|---------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 75bbbls |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | | Adequate |
| Comment: | in same berm system as crude tank | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.200304,-104.750295 |
| Comment: | HSR Fogelman and HSR Russel name painted over on battery sign as wells P&A. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------|--|--|
| Yes/No | | |
|--------|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------------|---|
| 697600676 | wellhead and sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013925 |
| 697600677 | battery sign, crude and PW tanks | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013926 |
| 697600678 | separator, ECD and GMRs | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013927 |