

Inspection Photos
Location Name: State PC GC 36-16
Location ID: 417830



Photo 1 – Tank Battery



Photo 2 – West Tank, NFPA Label is peeling and Capacity Label is missing



Inspection Photos
Location Name: State PC GC 36-16
Location ID: 417830




Photo 3 – Stained Soil at Wellhead



Photo 4 – Trash, unused belt

Inspection Photos
Location Name: State PC GC 36-16
Location ID: 417830



Photo 5 – Unused Containment

Photo 4 – Trash, unused belt