

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 1 – Tank Battery



Photo 2 – West Wellhead – Sign Missing

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 3 – East Wellhead – Sign Missing