

# *Inspection Photos*

*Loc#335163*

*Operator: Caerus*

*Inspection Number: 692401684*

*Inspection Date: 12/10/19*





Photo#1:  
Overview of Location to North.

December 10, 2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#335163



Photo#2:  
Area of Cheat grass establishment.



Photo#3:  
Area of Cheat grass establishment.

December 10, 2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#335163



Photo#4:  
Successful Interim area.



Photo#5:  
Stormwater BMP installation.

December 10, 2019