

Final Reclamation Inspection

December 11, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 332974

Inspection Document #: 697500910

Weld County, CO

NWSW Section 4 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DUKE USX J
Location ID: 332974



Photo 1. Photo taken from the Duke USX location. Photo illustrates only one well remains, as the other seven have been plugged and abandoned; therefore, this is a well release on an active location.

Inspection Photos
Location Name: DUKE USX J
Location ID: 332974



Photo 2. Photo taken from the location, facing East. See comments under Photo 1.