

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2019

Submitted Date:

12/16/2019

Document Number:

694900944**FIELD INSPECTION FORM**

Loc ID 334962	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 20 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>GRIZZLY OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	
Grizzly		scollett@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267006	WELL	PR	03/01/2011	GW	045-09192	MILLER 5-36	PR
267007	WELL	PR	10/01/2010	GW	045-09191	MILLER 4-36	PR
412889	WELL	PR	06/09/2010	GW	045-18680	MILLER 23D-36-692	PR
412890	WELL	PR	06/09/2010	GW	045-18681	MILLER 22A-36-692	PR
412891	WELL	PR	06/15/2010	GW	045-18682	MILLER 23C-36-692	PR
412892	WELL	PR	06/09/2010	GW	045-18683	MILLER 13D-36-692	PR
412893	WELL	PR	06/17/2010	GW	045-18684	MILLER 13C-36-692	PR
412894	WELL	PR	05/27/2010	GW	045-18685	MILLER 12D-36-692	PR
412895	WELL	PR	05/12/2010	GW	045-18686	MILLER 12C-36-692	PR
412896	WELL	PR	05/27/2010	GW	045-18687	MILLER 11A-36-692	PR
412897	WELL	PR	05/27/2010	GW	045-18688	MILLER 11B-36-692	PR
412898	WELL	PR	05/12/2010	GW	045-18689	MILLER 11D-36-692	PR
412899	WELL	PR	06/17/2010	GW	045-18690	MILLER 12A-36-692	PR

General Comment:

COGCC Inspection Report Summary
 On Monday 12/16/19 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Miller 1, at Location # 334962 in Garfield County, Colorado.
 While there, I observed normal production operations.
 This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 13		corrective date
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	chemical tanks		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	OTHER	HEATED STEEL AST		,
Comment:	625 Bbl tanks one (1) tank is not heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	267006	Type:	WELL	API Number: 045-09192	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	267007	Type:	WELL	API Number: 045-09191	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	412889	Type:	WELL	API Number: 045-18680	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	412890	Type:	WELL	API Number: 045-18681	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	412891	Type:	WELL	API Number: 045-18682	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	412892	Type:	WELL	API Number: 045-18683	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	412893	Type:	WELL	API Number: 045-18684	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	412894	Type:	WELL	API Number: 045-18685	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:

Facility ID:	412895	Type:	WELL	API Number:	045-18686	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	412896	Type:	WELL	API Number:	045-18687	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	412897	Type:	WELL	API Number:	045-18688	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	412898	Type:	WELL	API Number:	045-18689	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	412899	Type:	WELL	API Number:	045-18690	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Sediment Traps				
Berms		Check Dams				
Ditches		Culverts				
		Rip Rap				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900949	694900944	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5014634