

Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Colorado Oil & Gas Conservation Commission
40.63321, -104.73518, 1509.0m, 245°
12/13/2019 10:56:14

Signage at entrance

Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Colorado Oil & Gas Conservation Commission
40.63246, -104.73595, 1513.0m, 184°
12/12/2019 23:28:40

Water storage tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Colorado Oil & Gas Conservation Commission
40.63261, -104.73619, 1520.0m, 26°
12/13/2019 10:38:15

Fuel storage, note: no grounding



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Vapor line fluid knock out. Note: No grounding



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Colorado Oil & Gas Conservation Commission
40.63251, -104.73568, 1518.0m, 290°
12/13/2019 10:28:32

Oil tanks



Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Combustor



Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Aerial of location



Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Well testing separators



Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Water Tanks



Inspection Photos
Location Name: Simpson Pad 26 Pad
Location ID: 457767



Oil tanks

