

Inspection Photos

Loc#311651

Operator: Ursa

Inspection Number: 692401688

Inspection Date: 12/10/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

December 10, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Snyder Loc#311651



Photo#2:

Wildlife Escape Board in cellar of Well #045-11917 is improperly adjusted.

December 10, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Snyder Loc#311651