

Pit Status Evaluation Form

Pit Overview:

Pit Name: Welker 43-30	Facility ID: 119075
Current Status: Unknown	Status Date: 09/23/1999
Current Operator: Markus Production	
Updated Operator: Markus Production	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: Location 313907, Pit 109716, API 05-087-07832	

County: Morgan			
Township: 5N	Range: 60W	Section: 30	QQ: NESE
Original Latitude/ Longitude: 40.370138 / -104.130691			
Updated Latitude/ Longitude: 40.372011 / -104.131236			
Basis for Location Change: Location not changed			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes: 	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 158755 | Date: 05/31/1995 |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input checked="" type="checkbox"/> | Form 4 Sundry Notice – Doc #: 684795 | Date: 06/10/1997 |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Pit Status Review Summary:

Pit apparent in 1989 photo; Pit appears closed pre-1995, field inspection indicates use of fiberglass tank.