

Inspection Photos
Location Name: Roth /44-30
Location #: 419018



Photo #1
Rothe 44-30 (05-123-32101) Wellsite
Temporarily Abandoned | TA
Sign with well name NOT posted
prior insp.



Photo #2
Rothe 44-30 Wellsite
Temporarily Abandoned | TA
Sign with well name NOW posted

Inspection Photos
Location Name: Roth /44-30
Location #: 419018



Photo #3
Rothe 43-30, 44-30 Battery
Shut-down | Inactive
prior insp.