

Inspection Photos
Operator: Rim Operating
Location/API #: 067-09185
Date: 12-13-2019



Photo 1. View of the project area from the northern edge facing center.



Photo 2. View of the eastern project area from the northern corner facing southeastward. Revegetation is progressing with western wheatgrass and sand dropseed in a dormant vegetative condition. Cattle present in adjacent pasture.



Photo 3. View of reference area, comprised of an irrigated grass field in a mowed/dormant vegetative condition.