

Inspection Photos
Location Name: HSR Moser 13-4A
Location ID: 330744



Photo 1 WH sign

Photo 2 Weed appear to have been cut

Inspection Photos
Location Name: HSR Moser 13-4A
Location ID: 330744



Photo 3 Weed appear to have been cut behind WH