

Reclamation Inspection

December 17, 2019

Operator: HIGHPOINT OPERATING CORPORATION - 10071

Location ID: 318696

Inspection Document #: 697500916

Weld County, CO

NWSE Section 1 T1N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MARTIN #1
Location ID: 318696




Photo 1. Photo taken from the central location, facing Northwest. Photo illustrates weed management has been performed.

Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 2. Photo taken from the central location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 3. Photo taken from the northwestern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 4. Photo taken from the northeastern location, facing South. See comments under Photo 1.