

Reclamation Inspection

December 17, 2019

Operator: HIGHPOINT OPERATING CORPORATION - 10071

Location ID: 318020

Inspection Document #: 697500918

Weld County, CO

NWNE Section 24 T2N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CUYKENDALL "C" #3
Location ID: 318020



Photo 1. Photo taken from the eastern tank battery location, facing North. Photo illustrates unmanaged weeds.



Inspection Photos
Location Name: CUYKENDALL "C" #3
Location ID: 318020



Photo 2. Operator sign at the eastern tank battery is not accurate.



Photo 3. Operator sign at the eastern tank battery was corrected after COGCC staff met with an Operator representative on location.

Inspection Photos
Location Name: CUYKENDALL "C" #3
Location ID: 318020



Photo 4. Photo taken from the eastern tank battery location, facing Southwest. See comments under Photo 1.

Inspection Photos
Location Name: CUYKENDALL "C" #3
Location ID: 318020



Photo 5. Photo taken from the eastern tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CUYKENDALL "C" #3
Location ID: 318020



Photo 6. Photo taken from the western tank battery location, facing South. See comments under Photo 1.