

Inspection Photos
Location Name: DOW-65N63W /28NESE
Location #: 331381



Photo #1
DOW 43-28 Battery site
Abandoned | Most equipment removed
Reclamation progressing
*Unused Gas meter run
prior insp.*



Photo #2
DOW 43-28 Battery site
Abandoned | ALL equipment removed
Reclamation progressing
Unused Gas meter run: Removed

Inspection Photos
Location Name: DOW-65N63W /28NESE
Location #: 331381



Photo #3
DOW 43-28 Wellsite
Plugged & Abandoned | PA
Junk & Trash

*Cut casing pipe, cement, plastic liner
prior insp.*



Photo #4
DOW 43-28 Wellsite
Plugged & Abandoned | PA
Junk & Trash

*Cut casing pipe, cement, plastic liner: **REMOVED***

Inspection Photos
Location Name: DOW-65N63W /28NESE
Location #: 331381



Photo #5
DOW 43-28 (05-123-20594) Wellsite
Plugged & Abandoned | PA
~ 15 yds.
Appears to be cut & capped
Reclamation progressing
prior insp.