

Inspection Photos
Location Name: LAURA-65N63W /28SENE
Location #: 305671



Colorado Oil & Gas Conservation Commission
40.37269, -104.43336, 1367.0m, 274°
11/19/2019 04:22:30 PM

Photo #1

Laura 8-28 Battery site
Abandoned | Most equipment removed
Reclamation progressing
*Unused Gas meter run
prior insp.*



Colorado Oil & Gas Conservation Commission
40.37268, -104.43342, 1367.0m, 281°
12/18/2019 10:58:06 AM

Photo #2

Laura 8-28 Battery site
Abandoned | ALL equipment removed
Reclamation progressing
Unused Gas meter run: REMOVED

Inspection Photos

Location Name: LAURA-65N63W /28SENE

Location #: 305671



Colorado Oil & Gas Conservation Commission
40.3725, -104.43372, 1367.0m, 189°
11/19/2019 04:21:02 PM

Photo #3

Laura 8-28 (05-123-23332) Wellsite

Plugged & Abandoned | PA

~ 15 yds.

Appears to be cut & capped

Reclamation progressing

prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources