

Inspection Photos

Location Name: 70 RANCH-65N63W /27NWSW

Location #: 305246



Photo #1

70 Ranch 13-27 Battery site

Abandoned | Most equipment removed.

Reclamation progressing

*Remove unused gas meter run
prior insp.*



Photo #2

70 Ranch 13-27 Battery site

Abandoned | Most equipment removed.

Reclamation progressing

Unused gas meter run: REMOVED

Inspection Photos

Location Name: 70 RANCH-65N63W /27NWSW

Location #: 305246



Photo #3

70 Ranch 13-27 (05-123-22704) Wellsite

Temporarily Abandoned | TA

prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources