

Inspection Photos
Location Name: Randall Creek 6-19H
Location ID: 418462



Colorado Oil and Gas Conservation Commission
40.98914, -104.35413, 5299.7ft, 225°
12/17/2019 12:55:34

Photo 1 – Pumping Unit



Colorado Oil and Gas Conservation Commission
40.98927, -104.35446, 5304.8ft, 121°
12/17/2019 12:55:55

Photo 2 – Wellhead Sign



Inspection Photos
Location Name: Randall Creek 6-19H
Location ID: 418462



Photo 3 – Tank Battery



Photo 4 – North Tank – NFPA label has faded

Inspection Photos
Location Name: Randall Creek 6-19H
Location ID: 418462



Photo 5 – NFPA label has faded



Photo 6 – NFPA label has faded

Inspection Photos
Location Name: Randall Creek 6-19H
Location ID: 418462



Photo 7 – NFPA label has faded

