

# *Inspection Photos*

*Loc#335305*

*Operator: Grizzly Operating*

*Inspection Number: 692401729*

*Inspection Date: 12/12/19*





Photo#1:  
Overview of location to Southeast.

December 12, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly GGU Loc#335305



Photo#2:  
Southern Interim Rec area.

December 12, 2019



Photo#3:  
Area behind Separators.

Inspection Photos: Grizzly GGU Loc#335305