

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402040929

Date Received:  
05/12/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Jessica Dooling

970-675-4122

jessica\_dooling@comcast.net

### COGCC INSPECTION SUMMARY:

FIR Document Number: 692400944

Inspection Date: 05/02/2019

FIR Submit Date: 05/06/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

### LOCATION - Location ID: 441601

Location Name: RNPU Number: 197-15A2H County: \_\_\_\_\_

Qtrqr: NWSE Sec: 15 Twp: 1S Range: 97W Meridian: 6

Latitude: 39.962811 Longitude: -108.266590

### FACILITY - API Number: 05-103- -00 Facility ID: 441601

Facility Name: RNPU Number: 197-15A2H

Qtrqr: NWSE Sec: 15 Twp: 1S Range: 97W Meridian: 6

Latitude: 39.962811 Longitude: -108.266590

### CORRECTIVE ACTIONS:

1 ☒ CA# 124899

Corrective Action: Install or repair required BMPs per Rule 1002.f. .

Date: 05/13/2019

Response: CA COMPLETED

Date of Completion: 05/10/2019

Operator Comment: BMPs installed 5/10/2019, see attached photos

COGCC Decision: Approved

Inspector has visited location since BMP Repairs.

COGCC  
Representative:

2 ☒ CA# 124900

Corrective Action: Install or repair required BMPs per Rule 1002.f. .

Date: 05/13/2019

Response: CA COMPLETED

Date of Completion: 05/10/2019

Operator  
Comment: BMPs installed, see attached photos

COGCC Decision: Approved

COGCC  
Representative: Inspector has visited location since BMP Repairs.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CAs completed, wattles installed around stockpiles, road repaired and gravel applied to access road.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed:

Title: Regulatory Coordinator

Date: 5/12/2019 6:52:38 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402040929	FIR RESOLUTION SUBMITTED
402040930	20190510 Gravel on Road Photo
402040931	20190510 Gravel on Road photo
402040932	20190510 Road Repaired
402040933	20190510 Wattles Installed

Total Attach: 5 Files