

Inspection Photos

Loc#418465

Operator: Grizzly

Inspection Number: 692401737

Inspection Date: 12/12/19





Photo#1:
Overview of location to West.

December 12, 2019



Photo#2:
Small cellars (housing lines/valves) adjacent to Main well cellars.



Photo#3:
Small cellars (housing lines/valves) adjacent to Main well cellars.

December 12, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly GGU Fed Loc#418465



Photo#4:
Interim Rec adjacent to entry on North side of site.

December 12, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly GGU Fed Loc#418465