

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS-EBUS

Interchange A S22-30-2N Surface

Sincerely,
Meghan Jacobs

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0 Cementing Job Summary 4

 1.1 Executive Summary4

2.0 Real-Time Job Summary 7

 2.1 Job Event Log7

3.0 Attachments..... 9

 3.1 Interchange A S22-30-2N Surface – Job Chart9

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Interchange A S22-30-2N** cement **Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 30 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 369404		Ship To #: 3901279		Quote #:		Sales Order #: 0905985273					
Customer: EXTRACTION OIL & GAS -						Customer Rep: Hans					
Well Name: INTERCHANGE A				Well #: S22-30-2N		API/UWI #: 05-014-20764-00					
Field: WATTENBERG		City (SAP): BROOMFIELD		County/Parish: BROOMFIELD		State: COLORADO					
Legal Description: SW NW-10-1S-68W-2172FNL-886FWL											
Contractor: ENSIGN DRLG					Rig/Platform Name/Num: ENSIGN 147						
Job BOM: 7521 7521											
Well Type: HORIZONTAL OIL											
Sales Person: HALAMERICA\HX38199					Srv Supervisor: Nikolaus Kornafel						
Job											
Formation Name											
Formation Depth (MD)		Top		Bottom							
Form Type					BHST						
Job depth MD		1631ft			Job Depth TVD		1631				
Water Depth					Wk Ht Above Floor						
Perforation Depth (MD)		From		To							
Well Data											
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft	
Casing	0	9.625	8.921	36			0	1631	0	1631	
OH		13.5					0	1636	0	1636	
Tools and Accessories											
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make		
Guide Shoe	9.625	1		1631		Top Plug	9.625	1	HES		
Float Collar	9.625	1		1588							
						Plug Container	9.625	1	HES		
						Centralizers	9.625				
Fluid Data											
Stage/Plug #: 1											
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	SPACER	Red Dye Spacer			10	bbl	8.33			5	

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	CEMENT	SWIFTCEM (TM) SYSTEM	600	sack	13.5	1.74	9.17	8	5,502
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Fresh Water	Fresh Water	123	bbl	8.33			8	
Cement Left In Pipe		Amount	42 ft		Reason			Shoe Joint	
Mix Water:	pH 7	Mix Water Chloride:	0 ppm			Mix Water Temperature:	69 °F		
Cement Temperature:	N/A	Plug Displaced by:	8.33 lb/gal			Disp. Temperature:	69 °F		
Plug Bumped?	Yes	Bump Pressure:	484 psi			Floats Held?	Yes		
Cement Returns:	30 bbl	Returns Density:	N/A			Returns Temperature:	N/A		
Comment Once the rig was done circulating they handed it over to Halliburton. We pumped a 10 BBL water spacer with red dye in it. Followed by 186 BBLS of our swiftcem cement at 13.5 Lb/Gal . We shut down after cement was pumped to drop the top plug, followed by 123 BBLS of fresh water displacement. Bumped plug at calculated displacement. Checked floats 1 BBL back to the truck. Floats held.									

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DS Pump Press (psi)	DH Density (ppg)	Comb Pump Rate (bbl/min)	Comments
Event	1	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	9/20/2019	14:15:00	USER				CREW DISCUSSED ROUTES, HAZARDS, AND COMMUNICATION WITH CREW.
Event	2	Crew Leave Yard	Crew Leave Yard	9/20/2019	14:30:00	USER				STARTED JOURNEY MANAGEMENT.
Event	3	Call Out	Call Out	9/20/2019	18:00:00	USER				CREW CALLED OUT AT 06:00, REQUESTED ON LOCATION 07:00. CREW PICKED UP CEMENT, CHEMICALS, AND PLUG CONTAINER FROM FT. LUPTON, CO. BULK 660 10025030, BULK 660 10867415, BULK 660 10025027 AND PUMP 11826999.
Event	4	Arrive at Location from Service Center	Arrive at Location from Service Center	9/20/2019	18:30:00	USER				MEET WITH CO. MAN TO DISCUSS JOB; SURFACE CASING- 9.625" 36 LB/FT @ 1,631', 13.5" OPEN HOLE 1,636', SHOE TRAC- 41', MUD WEIGHT 8.4 LB/GAL PUMP FRESH WATER DISPLACEMENT 123 BBLs. CASING LANDED @ 22:30 9/19/2019. RIG CIRCULATED BOTTOMS UP At 406 GPM at 106 PSI.
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	9/20/2019	19:00:00	USER				HAZARD HUNT. DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH LOCATION, RIG UP, AND WEATHER.
Event	6	Rig-Up Equipment	Rig-Up Equipment	9/20/2019	19:30:00	USER				CREW STAGED EQUIPMENT AND RIGGED UP BULK, IRON AND WATER HOSES TO PERFORM JOB.
Event	7	Pre-Job Safety Meeting	Pre-Job Safety Meeting	9/20/2019	23:00:00	USER	-1.00	8.42	0.00	SAFETY MEETING WITH HALLIBURTON, AND RIG PERSONNEL. CREW COMMUNICATED POTENTIAL SAFETY HAZARDS, AND JOB DETAILS.
Event	8	Start Job	Start Job	9/21/2019	00:19:17	COM11	-6.00	8.53	0.00	BEGIN RECORDING JOB DATA.
Event	9	Test Lines	Test Lines	9/21/2019	00:20:43	COM11	33.00	8.42	0.00	PRESSURE TESTED IRON TO 2,500 PSI. KICKOUTS SET @ 500 PSI, KICKED OUT @ 980 PSI, 5TH GEAR STALL OUT @ 1,430 PSI. AND THEN BROUGHT IT UP AND KICKED OUT @ 2440 PSI.

Event	10	Pump Spacer 1	Pump Spacer 1	9/21/2019	00:25:56	COM11	-1.00	8.42	0.00	PUMP 10 BBLS OF RED DYE SPACER AT PUMP RATE 5 BBLS/MIN @ 140 PSI.
Event	11	Pump Lead Cement	Pump Lead Cement	9/21/2019	00:29:50	COM11	21.00	8.38	0.00	PUMPED 600 SKS OF SWIFTCEM LEAD CEMENT @ 13.5 LB/GAL, 1.74 FT3/SK, 9.17 GAL/SK. 186 BBLS, TOP OF CEMENT @ SURFACE. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 450 PSI.
Event	12	Check Weight	Check Weight	9/21/2019	00:38:28	COM11	443.00	13.38	8.10	DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	13	Check Weight	Check Weight	9/21/2019	00:46:19	COM11	444.00	13.44	8.00	DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	14	Shutdown	Shutdown	9/21/2019	00:57:40	COM11	87.00	13.91	0.00	SHUTDOWN TO WASH UP
Event	15	Drop Top Plug	Drop Top Plug	9/21/2019	01:00:28	COM11	2.00	14.18	0.00	PLUG LEFT CONTAINER, VERIFIED BY CO. MAN.
Event	16	Pump Displacement	Pump Displacement	9/21/2019	01:00:40	COM11	2.00	14.18	0.00	BEGIN CALCULATED DISPLACEMENT OF 123 BBLS WITH FRESH WATER.
Event	17	Bump Plug	Bump Plug	9/21/2019	01:21:07	COM11	1134.00	8.38	0.00	PLUG BUMPED AT CALCULATED DISPLACEMENT. 482 PSI PRESSURED UP 500 PSI OVER FINAL CIRCULATING PRESSURE TO 1,000 PSI. 10 BBLS OF RED DYE SPACER TO SURFACE AND 30 BBLS OF CEMENT RETURNED TO SURFACE.
Event	18	Other	Other	9/21/2019	01:21:11	COM11	1135.00	8.38	0.00	RELEASED PRESSURE, FLOATS HELD, 1 BBL BACK.
Event	19	End Job	End Job	9/21/2019	01:22:26	COM11	-1.00	8.35	0.00	STOP RECORDING JOB DATA.
Event	20	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	9/21/2019	01:25:00	USER				DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH WEATHER, LOCATION AND RIGGING DOWN IRON AND HOSES.
Event	21	Rig-Down Completed	Rig-Down Completed	9/21/2019	02:30:00	USER				ALL HALLIBURTON ITEMS WERE STOWED FOR TRAVEL, AND LOCATION WAS CLEAN.
Event	22	Safety Meeting - Departing Location	Safety Meeting - Departing Location	9/21/2019	02:35:00	USER				CREW DISCUSSED ROUTES HAZARDS AND COMMUNICATION WITH CREW.
Event	23	Crew Leave Location	Crew Leave Location	9/21/2019	02:40:00	USER				THANK YOU FOR USING HALLIBURTON – NICK KORNAFEL AND CREW.

3.0 Attachments

3.1 Interchange A S22-30-2N Surface – Job Chart

