

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 3: Stained soil



Photo 4: Stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Colorado Oil and Gas Conservation Commission
40.46495, -104.84131, 1430.7m, 12°
Dec 23, 2019 09:58:10

Photo 7: Stained soil



Colorado Oil and Gas Conservation Commission
40.46494, -104.84125, 1430.6m, 356°
Dec 23, 2019 09:58:23

Photo 8: Wellhead Sign

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 9: Wellhead



Photo 10: Stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 11: Wellhead Sign



Photo 12: Wellhead

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Colorado Oil and Gas Conservation Commission
40.46494, -104.84119, 1427.4m, 340°
Dec 23, 2019 09:59:04

Photo 13: Stained soil



Colorado Oil and Gas Conservation Commission
40.46492, -104.84115, 1427.5m, 15°
Dec 23, 2019 09:59:13

Photo 14: Wellhead Sign

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 15: Wellhead




Photo 16: Stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 17: Equipment being removed



Photo 18: equipment begun to be disassembled for removal