

# Final Reclamation Inspection

December 19, 2019

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 426701

Inspection Document #: 697500939

Weld County, CO

Lot 3 Section 1 T7N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location: Bridgman #1-1H  
Location ID: 426701



12.19.2019 12:06

**Photo 1.** Photo taken from the western well pad, facing East. Photo illustrates the approximate location of the well left with surface casing. Operator has failed to plug and perform Final Reclamation.

Inspection Photos  
Location: Bridgman #1-1H



**Photo 2.** Close up photo taken from the well left with surface casing.

Inspection Photos  
Location: Bridgman #1-1H  
Location ID: 426701



**Photo 3.** Photo taken from the western well pad, facing Northeast. Photo illustrates Operator has failed to plug and perform Final Reclamation.



**Photo 4.** Photo taken from the western well pad, facing Southeast. See comments under Photo 3.

Inspection Photos  
Location: Bridgman #1-1H  
Location ID: 426701



**Photo 5.** Photo taken from the western well pad, facing South. Photo illustrates erosion and weed establishment along the east-facing topsoil stockpile.