

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2019

Submitted Date:

12/17/2019

Document Number:

697000290**FIELD INSPECTION FORM**Loc ID 324871 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 81480Name of Operator: THOMAS L SPRING LLCAddress: 7400 E ORCHARD RD STE 106-SCity: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Springs, Tom	303-771-1889 off/68710	T1spring@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213340	WELL	PR	09/01/2019	GW	061-06702	KERFOOT 13-27	PR

General Comment:

Routine Inspection

Location**Lease Road:**

Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign mounted to wellhead		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Wire fence around tank. Fence needs repaired		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter run 1600' N by Temple A-1		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		38.286790,-102.782110	
Comment:	Tank is empty at time of inspection					
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	110bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms need maintenance for capacity				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	213340	Type:	WELL	API Number:	061-06702	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is SI at time of inspection. Meter run is 1600' N by Temple A-1 (P&A well)								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Location and access are grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT