

**Inspection Photos**  
**Location Name: McCallum 154**  
**Location ID: 324722**



**Photo 1. Overview of location taken facing south.**



**Photo 2. Stained soil at wellhead. Rags stuffed into wellhead. Bucket of oily waste without containment in right hand background of photo.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: McCallum 154**  
**Location ID: 324722**



**Photo 3. Close-up of wellhead with rags stuffed into it.**



**Photo 4. Oily waste in bucket from photo 2.**

