

Pit Status Evaluation Form

Pit Overview:

Pit Name: WOOLLEY A-1	Facility ID: 118015
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: COTTON PETROLEUM CORP / 20500	
Updated Operator:	
Form 15 Pit Permit Doc #: 382960	Permit Date: 4/7/1983
Related Facilities: WOOLLEY A #1-7 (API 05-123-09093)	

County: WELD			
Township: 1N	Range: 68W	Section: 7	QQ: SWNE
Original Latitude/ Longitude: 40.068924 / -105.043065			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 382960 | Date: 4/7/1983 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 382961 | Date: 12/16/1986 |
| Doc #: 500163873 | Date: 7/1/1997 |
| Doc #: 200055218 | Date: 6/2/2004 |
| <input checked="" type="checkbox"/> Form 27 Remediation Workplan – Project #: 13366 | Date: 4/22/2019 |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2314546 | Date: 12/18/1995 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Pit was closed prior to 1995 pit inventory report

Pit Status Review Summary:

Based on records review the pit on location was replaced by a concrete vault prior to the 1995 pit inventory report. The concrete vault was replaced by a fiberglass tank, which was removed under remediation project number 13366. Pit status has been changed to Closed.