

Inspection Photos

12/09/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 455471
Weld County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 1: Photo taken from the southwest end (entrance) of the location, facing north. Photos 1-3 provide an overview of the location from North, northeast to east. Photos show production equipment has been removed from the location. Final reclamation activities appear to be in process.



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the east end of the location, facing north. Photo shows final reclamation activities appear to be in process; production equipment has been removed. Utility equipment has not been removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 5: Photo of the excavated area on the east end of the location. Photo shows soils on location.



Photo 6: Photo taken from the east end of the location. Photo shows Diffuse Knapweed remains on the location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 455471



Photo 7: Photo taken from the northeast end of the location, facing south. See comments under photo 1.



Photo 8: Photo taken from the northeast end of the location, facing west. See comments under photo 1.